Page 1

July 16, 2009 8:16:58 AM

Item ID:

D2989-5

D

**Revision ID:** Item Name: Rib

**Start Date:** 

07/17/2009

Start Qty: 4.00

Required Date: 07/22/2009

QC:

Req'd Qty: 4.00



Accept

Setup Start



**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Process Plan: MF

Date: 09-07-16. Tooling:

Date:

SPC (Y/N):

Date: Date:

Start Run

Stop



Sequence ID/ **Work Center ID**  Operation Description Set Up/ **Run Hours** 

Draw Number Draw Rev.

Plan Accept Oty Code

Reject **Qty** 

Reject Number Stamp

Draw Nbr

**Revision Nbr** 

D2989 Rev D

100

Large Fab Large Fab

Large Fab

Memo

Memo

1- pick D3166-3 to cut D2989-5 rib as per dwg D2989 using DT9442 jig 12remove identification markings 3- deburr

0.00

0.00



110

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00



120

Packaging Packaging

Identify as per dwg & Stock Location:

0.00

0.00

Jy 09/07/20



## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Dowt No	_											

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

NCR:		,	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	Verification	Approval	Approval				
DATE	STEP	Section A In	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
						<u>.</u> <u>.</u>					
			-								
		•									
					:						
	1										

NOTE: Date & initial all entries

#### Work Order ID 50576

July 16, 2009 8:16:58 AM

Item ID:

D2989-5

**Revision ID:** Item Name:

D Rib

**Start Date:** 

07/17/2009

Start Qty: 4.00

**Required Date: 07/22/2009** Req'd Qty: 4.00



Accept



Run

Setup Start

Stop



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

**Process Plan:** 

QC:

Date:

Date:

**Tooling:** 

SPC (Y/N):

Set Up/

0.00

0.00

**Run Hours** 

Date: Date:

Start



Stop

Sequence ID/

Work Center ID

130

QC

Quality Control

Memo

**Operation** Description

QC21- Final Inspection - Work Order Release

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
						:					

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

	,	WORK ORDER NON-CONFORMANCE (NCR)								
	Description of NC		Corrective Action Section B	Verification	Approval	Approval				
STEP Section A				Sign & Date	Section C	Chief Eng	QC Inspector			
					_					
				:						
			-							
	STEP	STEP Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Description of NC Section A Initial Action Description Sign & Verification Section C	STEP Description of NC Section A Section B Initial Action Description Sign & Verification Section C Chief Eng			

NOTE: Date & initial all entries

### **Picklist Print**

July 16, 2009 8:16:58 AM

Work Order ID: 50576

Parent Item:

D2989-5RevD

Parent Item Name: Rib



50033

Start Date: 07/17/2009

**Required Date:** 07/22/2009

Start Qty: 4.00

Required Qty: 4.00

Comments:									5	Start Qty: 4.00		Required Qty: 4.	00 Status
	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
	D3166-3RevA1	TIID IBID IN BINDDI (BB) 1181 IB	Manufactured	No			100	Each	8.0000	0.3368			

Basket Hoop

Warehouse	Loc Qty	Loc Code
<b>Location</b>		
Main Warehouse		
WA	8	
48429	2	×.

SAD 09-07-20 4

# **Dart Aerospace Ltd**

W/O: WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date:	

Part No:	PAR #: Fault Cat	egory: NCR:	Yes No DQA:	_ Date:
			QA: N/C Closed:	Date:
NCR:	WORK ORE	ER NON-CONFORMANCE (	NCR)	
		Corrective Action Section B		

		Description of NC		Corrective Action Section B	}	Verification	Annroyal	Annrovol
DATE	STEP	TEP Section A Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto	
						1		
·								
						-		
					:			

NOTE: Date & initial all entries

